

Immediate Advice of an Operating Incident

TPWS Activation

Date: 31/01/2023

Location: L296 Maryland - Up Electric

Platform 1

Known Details of Incident

Shenfield to Paddinton LL Service.

The driver of 9Y01
experienced a TPWS brake
activation whilst travelling
towards L296 on the Up
Electric (Maryland station). At
this time L296 was displaying
a signal at danger.

Immediate Advice for Drivers

- What measures do you have in place to reduce risks when approaching/driving under restrictive signals
- What PPS do you use to mitigate the risk of distraction and maintain concentration

Issued by: Driver Team Managers



Managers Name:

Initial Notice Case: Operational notice case

Move to Notice Case:

File to:

Reference Number:2023.01.31_AL_JO_202301

Date of Issue: 31/01/2023

Date first posted: 31/01/2023

Date to move: 07/01/2023

Date to file: